

STD EGTC Cranfield 1215z

Climb to FL250 and route via DTY and UPTON toward point "O";

Join satellite track at point "O", continue to point "E";

Conduct multiple runs btwn points "E" and "G" at varying alts (nominally FL140ft and FL6000);

For final southbound ("E" to "G") run, hold at "F" as necessary to coincide with satellite overpass at 1442;

At point "G", climb to to FL100 and continue to "O". Slight dogleg off satellite track to Point 39 to avoid Danger Area.

At UPTON, FL100 for return to home-base via points "PT01", REGSI, "PT05", and CIT.

ETA EGTC 1615z

Point F
Satellite overpass @ 1442

Point E

Operating area for satellite calibration between G and E

Point G

Point L

Point M

Point 39

Waypoint UPTON

Point O

Point 01

DTY Daventry

Point 5



